


Chimney Reinforcement Recommendations

for Classic Edge HDX Models



NOTE

- Additional bracing may be necessary in certain areas such as those subject to severe weather, winds, freezing rain, etc.
- Inspect all bracing bi-annually for integrity.

